Oil Field Environmental Incident Summary

Responsible Party: MUREX PETROLEUM CORPORATION **Well Operator:** MUREX PETROLEUM CORPORATION

Well Name: CARLSON 2-36

Field Name: BATTLEVIEW Well File #: 8000

Date Incident: 5/24/2015 Time Incident: 05:00 Facility ID Number:

County: WILLIAMS Twp: 159 Rng: 95 Sec: 36 Qtr: NE NW

Location Description:

Submitted By: William Jansky Received By:

Contact Person: Shannon Holter

363 N. Sam Houston Pkwy. E.

Suite 200

HOUSTON, TX 77060

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Units

Distance Nearest Water Well:
Type of Incident: Pipeline Leak

Spilled

Release Contained in Dike: No Reported to NRC: No

Recovered Units

Followup

Units

Oil	1	Barrels	1	Barrels
Brine	8	Barrels	4	Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Release on ROW and on cultivated field

Potential Environmental Impacts:

Minimal, all ponded fluids were recovered. The area has booms and dikes to contain spread in event of rain.

Action Taken or Planned:

Upon discovery the well was shut in. Vacuum truck was called to removed ponded fluid. The area was diked and absorbent booms put down to prevent spread of contamination. The flowline has been flushed with freshwater. The old flowline will be plugged and replaced. Cleanup to be handled by third party remediator.

Wastes Disposal Location: Fluids were put in production tanks. Solids will go to PDI.

Agencies Involved:

Updates

Date: 5/27/2015 Status: Reviewed - Follow-up Required Author: Washek, Sandi

Updated Oil Volume: 1.00 barrels

Updated Salt Water Volume: 8.00 barrels

Updated Other Volume:

Updated Other Contaminant

Notes:

According to incident summary, material was released off site and impacted a cultivated field. Followup required.

Date: 8/13/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 15:21 8/13/2015.

No sign of spill at the time of inspection. Impacted field has good crop ready for harvest.

No followup is necessary.